School Infrastructure		
- III. A.		Estimated Cost
Facility Name	Item Description	(With Inflation)
Clear Brook High School	Access gates at tennis courts for lighting preventive	933
_	maintenance.	
Clear Brook High School	Lighting - Kitchen	122,472
Clear Brook High School	Lighting - Exterior	349,920
Clear Brook High School	Replace reach-in cooler (single door).	52,488
Clear Brook High School	Replace reach-in cooler (double door).	27,702
Clear Brook High School	Replace convection oven.	90,979
Clear Brook High School	Replace Combi Oven	70,397
Clear Brook High School	Kitchen Hoods	122,472
Clear Brook High School	Weight Room - Trane CHW SZAHU/MZAHU - (1997)	90,979
Clear Brook High School	Trane MZAHUs + OAHUs (1997) -Areas L/M	3,645,000
Clear Brook High School	Set Shop - AHU	87,480
Clear Brook High School	RayPak DHW Boiler - Central Plant - (2006)	87,480
Clear Brook High School	EvapCo Cooling Tower (2005)	163,296
Clear Brook High School	DX RTUs - Gym 3 (Practice) + Dance Studio - Trane	396,576
-	(2006)	
Clear Brook High School	CWHW Pumps (1997) - Air-Cooled Chillers/Outside Boiler	303,264
Clear Brook High School	CW/HW Pumps - B-2 + Chiller 1-D	233,280
Clear Brook High School	Condenser Water Piping	262,440
Clear Brook High School	DX RTUs - Gyms 1 - (2010)	594,864
Class Break High Cabaal	Replace existing domestic boiler in the football storage	145.000
Clear Brook High School	area boiler room.	145,800
Clear Brook High School	Galvanized Piping	3,695,144
Clear Brook High School	Domestic Water - Backflow Preventer	11,664
Clear Brook High School	Athletics - Sink + Drain (Training Room)	29,160
Clear Brook High School	MDF	58,320
Clear Brook High School	IDF9 - Across from Rm 418 - 2nd floor	58,320
Clear Brook High School	IDF8 - Across from Rm 402 - 2nd floor	58,320
Clear Brook High School	IDF7 - Across from Rm 316 - 1st floor	58,320
Clear Brook High School	IDF6 - Across from Rm 304 - 1st floor	58,320
Clear Brook High School	IDF4 - Storage in Rm 500	58,320
Clear Brook High School	IDF17 - BB Pressbox	87,480
Clear Brook High School	IDF16 - SB Pressbox	87,480
Clear Brook High School	IDF15 - Conc Stand	87,480
Clear Brook High School	IDF14 - Football Pressbox	87,480
Clear Brook High School	IDF12 - Dance/Gym	87,480
Clear Brook High School	IDF11 - AG	87,480
Clear Brook High School	IDF10 - Library	58,320
Clear Brook High School	IDF1 - Gym hallway	58,320
Clear Brook High School	IDF Rack - Band/Fine Arts Area	58,320
	Clear Brook High School Total	11,633,550

School Infrastructure		
Facility Name	Item Description	Estimated Cost (With Inflation)
Clear Creek High School	Reseal all windows and control joints.	180,034
Clear Creek High School	Replace existing EPDM roof with modified bitumen roof.	384,501
Clear Creek High School	Control joint sealant	128,596
Clear Creek High School	Access gates at tennis courts for lighting preventive maintenance.	1,029
Clear Creek High School	Replace convection oven.	28,571
Clear Creek High School	Domestic Boiler - Teledyne Laars - Main Mechanical - Room B129 (1994)	96,447
Clear Creek High School	CWPs/PCHWPs/SCHWPs -(2006)	385,787
Clear Creek High School	Central Plant	160,745
Clear Creek High School	Boiler B-2 - AJAX - Band Hall Addition CP	43,401
Clear Creek High School	Athletics - 180 Ton Air-Cooled Chiller (2007)	231,472
Clear Creek High School	ACCH-1 - Air-Cooled Chiller (Band Hall) - Carrier (1995)	156,887
Clear Creek High School	(2) McQuay Water-Cooled Chillers - (2005) CH-01, CH-02	642,978
Clear Creek High School	Evapco Cooling Towers (2 Cells) - (2006)	180,034
Clear Creek High School	Water Piping - Galvanized	32,149
Clear Creek High School	Domestic EWH - AO Smith - (2006)	43,401
Clear Creek High School	(1) Rheem (2010) - 40 gallons - Domestic Water Heater - Carlisle Gym Area	43,401
Class Crask High Cabaal	•	12.000
Clear Creek High School	Domestic Water - Backflow	12,860
Clear Creek High School	MDF RM B126	64,298
Clear Creek High School	IDF-8 RM B217	64,298
Clear Creek High School	IDF-7 RM G114	64,298
Clear Creek High School	IDF-6 RM J301A (Band Area)	64,298
Clear Creek High School	IDF-5 RM F111 (Art outdoor area)	64,298
Clear Creek High School	IDF-4 RM D115A	64,298
Clear Creek High School	IDF-3 RM E115	64,298
Clear Creek High School	IDF21 - BB Conc Stand	96,447
Clear Creek High School	IDF20 - SB Pressbox	96,447
Clear Creek High School	IDF-2 RM C115	64,298
Clear Creek High School	IDF-18 BASEBALL BUILDING	96,447
Clear Creek High School	IDF-17 TICKET BOOTH	96,447
Clear Creek High School	IDF-16 RM E130A (Extended Science Wing)	96,447
Clear Creek High School	IDF-11 RM D216	64,298
Clear Creek High School	IDF-10 RM E214	64,298
Clear Creek High School	IDF-1 RM 119A	64,298
Clear Creek High School	IDF- 9 RM C216	64,298
	Clear Creek High School Total	4,006,104

School Infrastructure		
Facility Name	Item Description	Estimated Cost (With Inflation)
	<u> </u>	
Clear Falls High School	Control Joint Sealant	180,034
Clear Falls High School	Access gates at tennis courts for lighting preventive maintenance.	1,029
Clear Falls High School	Exterior Lighting	321,489
Clear Falls High School	HVAC Mechanical - Motor Starters (SZAHUs and Pumps)	225,042
Clear Falls High School	Replace Fill - Cooling Towers - (2008/2009)	270,051
Clear Falls High School	Domestic Water - Back Flow Preventer	12,860
Clear Falls High School	Domestic Water Heaters (AO Smith - 2009)	260,406
Clear Falls High School	IDF1 RM 4039	64,298
Clear Falls High School	IDF11 (next to concession stand)	96,447
Clear Falls High School	IDF12 (under softball pressbox)	96,447
Clear Falls High School	IDF2 RM 4871	64,298
Clear Falls High School	IDF3 RM 4814	64,298
Clear Falls High School	IDF4 RM 4508	64,298
Clear Falls High School	IDF5 RM 4405	64,298
Clear Falls High School	IDF6 RM 4222B (PLTW Area)	64,298
Clear Falls High School	IDF7 RM 4153 (ORCH)	64,298
Clear Falls High School	IDF8 RM 5507A	64,298
Clear Falls High School	IDF9 RM 5405A	64,298
Clear Falls High School	MDF RM 4050	64,298
<u> </u>	Clear Falls High School Total	2,106,785
	-	
Clear Lake High School	Replace existing modified bitumen roof at locker rooms	2,050,247
Clear Lake High School	Interior Lighting - Kruger Field House	149,010
Clear Lake High School	Replace Fill Material - (3) Cell EVAPCO Cooling Towers - (2013/2014)	278,152
Clear Lake High School	Football Area 2000 Addition - (2) CW York AHUs - VAV w/ Electric Reheat	2,066,274
Clear Lake High School	(2) McQuay Chillers Air Cooled - (2005) - Field House	662,267
Clear Lake High School	Domestic Water - Backflow Preventer	13,245
Clear Lake High School	IDF18 Baseball Pressbox	99,340
Clear Lake High School	IDF17 Football/Track	99,340
Clear Lake High School	IDF 7 (Science Pod Rm214)	99,340
Clear Lake High School	IDF 19 Softball Pressbox	99,340
Clear Lake High School	IDF 1 - (Field House)	66,227
	Clear Lake High School Total	5,682,782

School Infrastructure		
Facility Name	Item Description	Estimated Cost (With Inflation)
Clear Path Alternative High School	Exterior Lighting - Replace HID wall pack fixtures and canopy fixtures with LED fixtures	20,777
Clear Path Alternative High School	MDF-A	58,320
	Clear Path Alternative High School Total	79,097
Clear Springs High School	Access gates at tennis courts for lighting preventive maintenance.	1,060
Clear Springs High School	Replace HID parking lot fixtures, wall packs, and canopy fixtures with new LED.	331,134
Clear Springs High School	Upgrade to Lutron interior lighting controls.	1,560,361
Clear Springs High School	Upgrade isomet systems to current district standards (refer to Clear Lake HS).	59,604
Clear Springs High School	Decoupled loop has no EMS controlled bypass.	397,360
Clear Springs High School	MDF Rm 1030 (Library)	66,227
Clear Springs High School	IDF9 (F area classrooms upstairs)	66,227
Clear Springs High School	IDF8A (K area classroom downstairs)	66,227
Clear Springs High School	IDF7 (J area/Auto Shop Area)	66,227
Clear Springs High School	IDF5 (F area classroom downstarirs)	66,227
Clear Springs High School	IDF4 (Off Main Hall)	66,227
Clear Springs High School	IDF3 (Locker Rm Hallway)	66,227
Clear Springs High School	IDF2 (inside Sm Gym)	66,227
Clear Springs High School	IDF11 (Spring Sports Concession Building)	99,340
Clear Springs High School	IDF10 (K area classrooms upstairs)	66,227
	Clear Springs High School Total	3,044,902
Bayside Intermediate	Control joint sealant	91,854
Bayside Intermediate	Replace HID parking lot fixtures, wallpack fixtures and canopy fixtures with LED.	306,180
Bayside Intermediate	Replace fluorescent lighting in the kitchen areas with LED.	30,618
Bayside Intermediate	Replace cooling tower fill	79,607
Bayside Intermediate	Install insulated dog house over domestic water backflow preventer.	12,247
Bayside Intermediate	MDF RM 2051	61,236
Bayside Intermediate	IDF3 RM 2230	61,236
Bayside Intermediate	IDF2 RM 3006	61,236
Bayside Intermediate	IDF1 RM 2143	61,236
	Bayside Intermediate Total	765,450

School Infrastructure		
SCHOOL IIII astructure Estimated Cost		
Facility Name	Item Description	(With Inflation)
		,
	Remove and replace existing ADA ramp leading from	
Brookside Intermediate	staff parking up to building with three proposed ADA	23,328
	ramps with truncated dome's and one 5' x 5' concrete	
	landing.	
Brookside Intermediate	Regrade swells to ensure positive drainage towards storm sewer system.	17,496
Brookside Intermediate	Regrade swale in front of marquee.	11,664
	Provide clear ADA path leading from ADA parking spots	
Brookside Intermediate	up to bus drop off.	23,328
	Replace HID parking lot fixtures, wall pack fixtures, and	224.522
Brookside Intermediate	canopy fixtures with LED fixtures.	291,600
Brookside Intermediate	Replace Trane water-cooled chiller (2005)	554,040
Brookside Intermediate	Building-wide exhaust fan replacement.	148,859
Brookside Intermediate	Replace Raypak domestic water boiler and storage tank	145 900
brookside intermediate	(2011)	145,800
Brookside Intermediate	Replace domestic water mixing valves in boiler room	21,578
	·	,
Brookside Intermediate	Replace all drinking fountains building/campus-wide.	180,792
Brookside Intermediate	Replace (5) out of (6) suspended domestic water	96,228
brookside intermediate	heaters in academic wing	90,228
Brookside Intermediate	Install insulated dog house over domestic water	11,664
	backflow preventer.	,
Brookside Intermediate	Add trap primers to floor drains in commons mezzanine and main mechanical room	46,656
Brookside Intermediate	MDF (Library)	58,320
Brookside Intermediate	IDF3 Rm 161A	58,320
Brookside Intermediate	IDF1 Band/Gym HW Mech Rm/Elec Rm	58,320
	Brookside Intermediate Total	1,747,993
	Decree and realize ADA and the CO	
Clear Creek Intermediate	Remove and replace ADA ramp with three (3) new ADA	24,494
Clear Creek Intermediate	ramps and one (1) 5' x 5' landing. Regrade swale adjacent to bus drive.	18,371
Clear Creek Intermediate	Replace roof mounted exhaust fans.	165,223
Clear Creek Intermediate	Replace central plant pumps and add VFDs.	122,472
Clear Creek Intermediate	Building-wide outside air upgrade	428,652
Clear Creek Intermediate	Building-wide heat pump replacement, except 2020	3,426,786
	Fine Arts addition	
Clear Creek Intermediate	Building-wide ductwork replacement	3,212,612

Clear Creek Intermediate IDF5 RM 174A NEW LABS AREA 61,236 Clear Creek Intermediate IDF5 RM 174A NEW LABS AREA 61,236 Clear Creek Intermediate IDF5 RM 174A NEW LABS AREA 61,236 Clear Creek Intermediate IDF5 RM 174A NEW LABS AREA 61,236 Clear Creek Intermediate IDF5 RM 174A NEW LABS AREA 61,236 Clear Creek Intermediate IDF5 RM 174A NEW LABS AREA 61,236 Clear Creek Intermediate IDF3 RM 227 CHOIR AREA 61,236 Clear Creek Intermediate IDF3 RM 227 CHOIR AREA 61,236 Clear Creek Intermediate IDF2 RM 151 BOY COACH OFC 61,236 Clear Creek Intermediate IDF2 RM 151 BOY COACH OFC 61,236 Clear Creek Intermediate Control joint sealant. 128,596 Clear Lake Intermediate Control joint sealant. 128,596 Clear Lake Intermediate Replace existing modified bitumen roof. 4,791,472 Clear Lake Intermediate Regrade grass areas around tennis courts to ensure positive drainage to storm sewer system. 77,157 Clear Lake Intermediate Replace fan coil unit serving counts to ensure positive drainage to storm sewer system. 77,157 Clear Lake Intermediate Replace fan coil unit serving counts didition (2007, 15 year average life cycle) 192,893 Clear Lake Intermediate Replace DX rooftop serving original band hall (2007). 192,893 Clear Lake Intermediate Replace DX rooftop serving original classroom area 353,638 Clear Lake Intermediate Replace dual duct boxes serving promons/ stage (2007). 257,191 Clear Lake Intermediate Replace DX rooftop serving commons/ stage (2007). 257,191 Clear Lake Intermediate Replace dual duct boxes serving original classroom area 353,638 Clear Lake Intermediate Replace dual duct doxes serving original classroom area 353,638 Clear Lake Intermediate Replace dual duct doxes serving original classroom area 353,638 Clear Lake Intermediate Building-wide exhaust fan replacement 14,807 Clear Lake Intermediate Replace (2) DX rooftop serving commons/ stage (2007). 257,191 Clear Lake Intermediate Building-wide exhaust fan replacement 14,807 Clear Lake Intermediate DF5-Rm 1727 (Band Area) 64,298 Clear Lake Intermediate IDF5-Rm 1727 (Band Ar	School Infrastructure		
Clear Creek Intermediate room showers MDF-RM 317 ADMIN AREA 61,236 (Clear Creek Intermediate IDF6 New wing addition 61,236 (Clear Creek Intermediate IDF6 New wing addition 61,236 (Clear Creek Intermediate IDF5 RM 174A NEW LABS AREA 61,236 (Clear Creek Intermediate IDF3 RM 274 CHOIR AREA 61,236 (Clear Creek Intermediate IDF3 RM 227 CHOIR AREA 61,236 (Clear Creek Intermediate IDF3 RM 227 CHOIR AREA 61,236 (Clear Creek Intermediate IDF2 RM 151 BOY COACH OFC 61,236 (Clear Creek Intermediate IDF2 RM 151 BOY COACH OFC 61,236 (Clear Creek Intermediate IDF3 RM 22 CROSS FROM LIBRARY 61,236 (Clear Creek Intermediate IDF3 RM 24 CROSS FROM LIBRARY 61,236 (Clear Lake Intermediate Control joint sealant. 128,596 (Clear Lake Intermediate Replace existing modified bitumen roof. 4,791,472 (Clear Lake Intermediate Control joint sealant. 128,596 (Clear Lake Intermediate Regrade swells located behind school between staff parking lot and the school. Regrade grass areas around tennis courts to ensure positive drainage to storm sewer system. 77,157 (Clear Lake Intermediate Replace fan coil unit serving rooms 119/121 28,934 (Clear Lake Intermediate Replace fan coil unit serving rooms 119/121 28,934 (Clear Lake Intermediate Replace DX rooftop serving original band hall (2007). 192,893 (Clear Lake Intermediate Replace DX rooftop serving original band hall (2007). 192,893 (Clear Lake Intermediate Replace DX rooftop serving original classroom area 353,638 (Clear Lake Intermediate Replace dual duct boxes serving original classroom area 353,638 (Clear Lake Intermediate Replace grease trap 109,306 (Lear Lake Intermediate 1007) (Lear Lake Intermediate 100	Estimated Cost		
Clear Creek Intermediate Clear Creek Intermediate Clear Creek Intermediate MDF-RM 317 ADMIN AREA 61,236 Clear Creek Intermediate IDF6 New wing addition 61,236 Clear Creek Intermediate IDF3 RM 174A NEW LABS AREA 61,236 Clear Creek Intermediate IDF3 RM 201A DRAMA RM 61,236 Clear Creek Intermediate IDF3 RM 227 CHOIR AREA 61,236 Clear Creek Intermediate IDF2 RM 151 BOY COACH OFC 61,236 Clear Creek Intermediate IDF1 RM M-2 ACROSS FROM LIBRARY 61,236 Clear Creek Intermediate Clear Lake Intermediate Regrade swells located behind school between staff parking lot and the school. Clear Lake Intermediate Regrade grass areas around tennis courts to ensure positive drainage to storm sewer system. Clear Lake Intermediate Clear Lake Intermediate Replace fan coil unit serving rooms 119/121 28,934 Clear Lake Intermediate Replace DX split system serving band hall addition (2007, 15 year average life cycle) Clear Lake Intermediate Replace DX rooftop serving original band hall (2007). 192,893 Clear Lake Intermediate Replace DX rooftop serving original classroom area 353,638 Clear Lake Intermediate Replace DX rooftop serving original classroom area 353,638 Clear Lake Intermediate Replace DX rooftop serving commons/ stage (2007). 257,191 Clear Lake Intermediate Replace grease trap Install insulated dog house over domestic water backflow preventer. Clear Lake Intermediate MDF-Rm 116A Clear Lake Intermediate DiF5-Rm 127 (Band Area) Clear Lake In	racility Name	item bescription	(With Inflation)
Clear Creek Intermediate Clear Creek Intermediate Clear Creek Intermediate MDF-RM 317 ADMIN AREA 61,236 Clear Creek Intermediate IDF6 New wing addition 61,236 Clear Creek Intermediate IDF3 RM 174A NEW LABS AREA 61,236 Clear Creek Intermediate IDF3 RM 201A DRAMA RM 61,236 Clear Creek Intermediate IDF3 RM 227 CHOIR AREA 61,236 Clear Creek Intermediate IDF2 RM 151 BOY COACH OFC 61,236 Clear Creek Intermediate IDF1 RM M-2 ACROSS FROM LIBRARY 61,236 Clear Creek Intermediate Clear Lake Intermediate Regrade swells located behind school between staff parking lot and the school. Clear Lake Intermediate Regrade grass areas around tennis courts to ensure positive drainage to storm sewer system. Clear Lake Intermediate Clear Lake Intermediate Replace fan coil unit serving rooms 119/121 28,934 Clear Lake Intermediate Replace DX split system serving band hall addition (2007, 15 year average life cycle) Clear Lake Intermediate Replace DX rooftop serving original band hall (2007). 192,893 Clear Lake Intermediate Replace DX rooftop serving original classroom area 353,638 Clear Lake Intermediate Replace DX rooftop serving original classroom area 353,638 Clear Lake Intermediate Replace DX rooftop serving commons/ stage (2007). 257,191 Clear Lake Intermediate Replace grease trap Install insulated dog house over domestic water backflow preventer. Clear Lake Intermediate MDF-Rm 116A Clear Lake Intermediate DiF5-Rm 127 (Band Area) Clear Lake In			
Clear Creek Intermediate MDF-RM 317 ADMIN AREA 61,236 Clear Creek Intermediate IDF6 New wing addition 61,236 Clear Creek Intermediate IDF5 RM 174A NEW LABS AREA 61,236 Clear Creek Intermediate IDF3 RM 227 CHOIR AREA 61,236 Clear Creek Intermediate IDF3 RM 227 CHOIR AREA 61,236 Clear Creek Intermediate IDF2 RM 151 BOY COACH OFC 61,236 Clear Creek Intermediate IDF2 RM 151 BOY COACH OFC 61,236 Clear Creek Intermediate IDF1 RM M-2 ACROSS FROM LIBRARY 61,236 Clear Creek Intermediate Control joint sealant. 128,596 Clear Lake Intermediate Replace existing modified bitumen roof. 4,791,472 Clear Lake Intermediate Regrade swells located behind school between staff parking lot and the school. Clear Lake Intermediate Regrade grass areas around tennis courts to ensure positive drainage to storm sewer system. 77,157 Clear Lake Intermediate Replace fan coil unit serving coustodial office 28,934 Clear Lake Intermediate Replace DX split system serving band hall addition (2007, 15 year average life cycle) Clear Lake Intermediate Replace DX rooftop serving original band hall (2007). 192,893 Clear Lake Intermediate Replace dual duct boxes serving original classroom area 353,638 Clear Lake Intermediate Replace (2) DX rooftop serving commons/ stage (2007). 257,191 Clear Lake Intermediate Replace grease trap 109,306 Clear Lake Intermediate Replace grease trap 109,306 Clear Lake Intermediate NDF-Rm 116A 64,298 Clear Lake Intermediate IDF3-Rm 127 (Band Area) 64,298 Clear Lake Intermediate IDF3-Rm 127 (Band Area) 64,298 Clear Lake Intermediate IDF3-Rm 224A 64,298 Clear Lake Intermediate IDF3-Rm 128 64,298 Clear Lake Intermediate IDF3-Rm 127 (Band Area) 64,298 Clear Lake Intermediate IDF3-Rm 128 64,298 Clear Lake Intermediate IDF3-Rm 127 (Band Area) 64,298 Clear Lake Intermediate IDF3-Rm 16 Ft. Office Workroom 64,298	Clear Creek Intermediate		48.989
Clear Creek Intermediate IDF6 New wing addition 61,236 Clear Creek Intermediate IDF4 RM 201A DRAMA RM 61,236 Clear Creek Intermediate IDF3 RM 227 CHOIR AREA 61,236 Clear Creek Intermediate IDF2 RM 151 BOY COACH OFC 61,236 Clear Creek Intermediate IDF1 RM M-2 ACROSS FROM LIBRARY 61,236 Clear Creek Intermediate Replace existing modified bitumen roof. 4,791,472 Clear Lake Intermediate Replace existing modified bitumen roof. 4,791,472 Clear Lake Intermediate Regrade swells located behind school between staff 128,596 Clear Lake Intermediate Regrade swells located behind school between staff 12,860 Clear Lake Intermediate Regrade grass areas around tennis courts to ensure positive drainage to storm sewer system. 77,157 Clear Lake Intermediate Replace fan coil unit serving rooms 119/121 28,934 Clear Lake Intermediate Replace DX split system serving band hall addition (2007, 15 year average life cycle) 192,893 Clear Lake Intermediate Replace DX rooftop serving original band hall (2007). 192,893 Clear Lake Intermediate Replace DX rooftop serving original classroom area 353,638 Clear Lake Intermediat			
Clear Creek Intermediate IDF5 RM 174A NEW LABS AREA 61,236 Clear Creek Intermediate IDF4 RM 201A DRAMA RM 61,236 Clear Creek Intermediate IDF3 RM 227 CHOIR AREA 61,236 Clear Creek Intermediate IDF1 RM M-21 CHORN AREA 61,236 Clear Creek Intermediate IDF1 RM M-2 ACROSS FROM LIBRARY 61,236 Clear Lake Intermediate Replace existing modified bitumen roof. 4,791,472 Clear Lake Intermediate Replace existing modified bitumen roof. 4,791,472 Clear Lake Intermediate Regrade swells located behind school between staff parking lot and the school. 12,860 Clear Lake Intermediate Regrade grass areas around tennis courts to ensure positive drainage to storm sewer system. 77,157 Clear Lake Intermediate Replace fan coil unit serving rooms 119/121 28,934 Clear Lake Intermediate Replace DX split system serving band hall addition (2007, 15 year average life cycle) 192,893 Clear Lake Intermediate Replace DX rooftop serving original band hall (2007). 192,893 Clear Lake Intermediate Replace daul duct boxes serving original classroom area 353,638 Clear Lake Intermediate Replace dual duct boxes serving commons/ stage (2007). 257,191			
Clear Creek Intermediate IDF4 RM 201A DRAMA RM 61,236 Clear Creek Intermediate IDF3 RM 227 CHOIR AREA 61,236 Clear Creek Intermediate IDF2 RM 151 BOY COACH OFC 61,236 Clear Creek Intermediate IDF2 RM 151 BOY COACH OFC 61,236 Clear Creek Intermediate IDF1 RM M-2 ACROSS FROM LIBRARY 61,236 Clear Creek Intermediate Clear Creek Intermediate Control joint sealant. 128,596 Clear Lake Intermediate Reglace existing modified bitumen roof. 4,791,472 Clear Lake Intermediate Regrade swells located behind school between staff parking lot and the school. Clear Lake Intermediate Regrade grass areas around tennis courts to ensure positive drainage to storm sewer system. Clear Lake Intermediate Replace fan coil unit serving rooms 119/ 121 28,934 Clear Lake Intermediate Replace fan coil unit serving sustodial office 28,934 Clear Lake Intermediate Replace DX split system serving band hall addition (2007, 15 year average life cycle) Clear Lake Intermediate Replace DX rooftop serving original band hall (2007). 192,893 Clear Lake Intermediate Replace DX rooftop serving original classroom area 353,638 Clear Lake Intermediate Replace (2) DX rooftop serving commons/ stage (2007). 257,191 Clear Lake Intermediate Replace (2) DX rooftop serving commons/ stage (2007). 257,191 Clear Lake Intermediate Replace grease trap 109,306 Clear Lake Intermediate Replace grease trap 109,306 Clear Lake Intermediate Install insulated dog house over domestic water backflow preventer. Clear Lake Intermediate IDF3-Rm 116A 64,298 Clear Lake Intermediate IDF4 - (new wing) 64,298 Clear Lake Intermediate IDF3-Rm 127 (Band Area) 64,298 Clear Lake Intermediate IDF3-Rm 127 (Band Area) 64,298 Clear Lake Intermediate IDF3-Rm 128 64,298 Clear Lake Intermediate IDF3-Rm 116 Ft. Office Workroom 64,298 Clear Lake Intermediate IDF3-Rm 116 Ft. Office Workroom 64,298		3	
Clear Creek Intermediate IDF3 RM 227 CHOIR AREA 61,236 Clear Creek Intermediate IDF2 RM 151 BOY COACH OFC 61,236 Clear Creek Intermediate IDF1 RM M-2 ACROSS FROM LIBRARY 61,236 Clear Lake Intermediate Replace existing modified bitumen roof. 4,791,472 Clear Lake Intermediate Control joint sealant. 128,596 Clear Lake Intermediate Regrade swells located behind school between staff parking lot and the school. Clear Lake Intermediate Regrade grass areas around tennis courts to ensure positive drainage to storm sewer system. 77,157 Clear Lake Intermediate Replace fan coil unit serving rooms 119/ 121 28,934 Clear Lake Intermediate Replace fan coil unit serving custodial office 28,934 Clear Lake Intermediate Replace DX rooftop serving original band hall (2007). 192,893 Clear Lake Intermediate Replace DX rooftop serving admin (2007). 192,893 Clear Lake Intermediate Replace QDX rooftop serving commons/ stage (2007). 257,191 Clear Lake Intermediate Replace grease trap 109,306 Clear Lake Intermediate Replace grease trap 109,306			
Clear Creek Intermediate IDF2 RM 151 BOY COACH OFC 61,236 Clear Creek Intermediate IDF1 RM M-2 ACROSS FROM LIBRARY 61,236 Clear Lake Intermediate Replace existing modified bitumen roof. 4,791,472 Clear Lake Intermediate Replace existing modified bitumen roof. 4,791,472 Clear Lake Intermediate Regrade swells located behind school between staff parking lot and the school. 12,860 Clear Lake Intermediate Regrade grass areas around tennis courts to ensure positive drainage to storm sewer system. 77,157 Clear Lake Intermediate Replace fan coil unit serving rooms 119/ 121 28,934 Clear Lake Intermediate Replace DX split system serving band hall addition (2007, 15 year average life cycle) 192,893 Clear Lake Intermediate Replace DX rooftop serving original band hall (2007). 192,893 Clear Lake Intermediate Replace DX rooftop serving original classroom area 353,638 Clear Lake Intermediate Replace dual duct boxes serving original classroom area 353,638 Clear Lake Intermediate Building-wide exhaust fan replacement 164,807 Clear Lake Intermediate Building-wide exhaust fan replacement 164,807 Clear Lake Intermediate MDF-Rm 116A <td< td=""><td></td><td></td><td></td></td<>			
Clear Creek Intermediate IDF1 RM M-2 ACROSS FROM LIBRARY 61,236 Clear Creek Intermediate Total 7,876,251 Clear Lake Intermediate Replace existing modified bitumen roof. 4,791,472 Clear Lake Intermediate Control joint sealant. 128,596 Clear Lake Intermediate Regrade swells located behind school between staff parking lot and the school. Clear Lake Intermediate Regrade grass areas around tennis courts to ensure positive drainage to storm sewer system. 77,157 Clear Lake Intermediate Replace fan coil unit serving rooms 119/ 121 28,934 Clear Lake Intermediate Replace fan coil unit serving custodial office 28,934 Clear Lake Intermediate Replace DX split system serving band hall addition (2007, 15 year average life cycle) Clear Lake Intermediate Replace DX rooftop serving original band hall (2007). 192,893 Clear Lake Intermediate Replace DX rooftop serving original classroom area 353,638 Clear Lake Intermediate Replace dual duct boxes serving original classroom area 353,638 Clear Lake Intermediate Replace (2) DX rooftop serving commons/ stage (2007). 257,191 Clear Lake Intermediate Building-wide exhaust fan replacement 164,807 Clear Lake Intermediate Replace grease trap 109,306 Clear Lake Intermediate Replace grease trap 109,306 Clear Lake Intermediate Diff - (new wing) 64,298 Clear Lake Intermediate IDF5-Rm 116A 64,298 Clear Lake Intermediate IDF5-Rm 127 (Band Area) 64,298 Clear Lake Intermediate IDF3-Rm 224A 64,298 Clear Lake Intermediate IDF3-Rm 224A Clear Lake Intermediate IDF3-Rm 118 64,298 Clear Lake Intermediate IDF1-Rm 16 Ft. Office Workroom 64,298			
Clear Lake IntermediateReplace existing modified bitumen roof.4,791,472Clear Lake IntermediateControl joint sealant.128,596Clear Lake IntermediateRegrade swells located behind school between staff parking lot and the school.12,860Clear Lake IntermediateRegrade grass areas around tennis courts to ensure positive drainage to storm sewer system.77,157Clear Lake IntermediateReplace fan coil unit serving rooms 119/12128,934Clear Lake IntermediateReplace fan coil unit serving custodial office28,934Clear Lake IntermediateReplace DX split system serving band hall addition (2007, 15 year average life cycle)192,893Clear Lake IntermediateReplace DX rooftop serving original band hall (2007).192,893Clear Lake IntermediateReplace DX rooftop serving original classroom area353,638Clear Lake IntermediateReplace dual duct boxes serving original classroom area353,638Clear Lake IntermediateReplace (2) DX rooftop serving commons/ stage (2007).257,191Clear Lake IntermediateBuilding-wide exhaust fan replacement164,807Clear Lake IntermediateBuilding-wide exhaust fan replacement164,807Clear Lake IntermediateMDF-Rm 116A64,298Clear Lake IntermediateIDF6 - (new wing)64,298Clear Lake IntermediateIDF6 - (new wing)64,298Clear Lake IntermediateIDF5-Rm 127 (Band Area)64,298Clear Lake IntermediateIDF2-Rm 12864,298Clear Lake IntermediateIDF3-Rm 224A64,298Clea			
Clear Lake Intermediate Clear	Clear Creek Intermediate		·
Clear Lake IntermediateControl joint sealant.128,596Clear Lake IntermediateRegrade swells located behind school between staff parking lot and the school.12,860Clear Lake IntermediateRegrade grass areas around tennis courts to ensure positive drainage to storm sewer system.77,157Clear Lake IntermediateReplace fan coil unit serving rooms 119/12128,934Clear Lake IntermediateReplace fan coil unit serving custodial office28,934Clear Lake IntermediateReplace DX split system serving band hall addition (2007, 15 year average life cycle)192,893Clear Lake IntermediateReplace DX rooftop serving original band hall (2007).192,893Clear Lake IntermediateReplace DX rooftop serving admin (2007).192,893Clear Lake IntermediateReplace dual duct boxes serving original classroom area353,638Clear Lake IntermediateReplace (2) DX rooftop serving commons/ stage (2007).257,191Clear Lake IntermediateBuilding-wide exhaust fan replacement164,807Clear Lake IntermediateReplace grease trap109,306Clear Lake IntermediateMDF-Rm 116A64,298Clear Lake IntermediateMDF-Rm 116A64,298Clear Lake IntermediateIDF6 - (new wing)64,298Clear Lake IntermediateIDF5-Rm 127 (Band Area)64,298Clear Lake IntermediateID		Clear Creek Intermediate Total	7,870,231
Clear Lake IntermediateControl joint sealant.128,596Clear Lake IntermediateRegrade swells located behind school between staff parking lot and the school.12,860Clear Lake IntermediateRegrade grass areas around tennis courts to ensure positive drainage to storm sewer system.77,157Clear Lake IntermediateReplace fan coil unit serving rooms 119/ 12128,934Clear Lake IntermediateReplace fan coil unit serving custodial office28,934Clear Lake IntermediateReplace DX split system serving band hall addition (2007, 15 year average life cycle)192,893Clear Lake IntermediateReplace DX rooftop serving original band hall (2007).192,893Clear Lake IntermediateReplace DX rooftop serving admin (2007).192,893Clear Lake IntermediateReplace dual duct boxes serving original classroom area353,638Clear Lake IntermediateReplace (2) DX rooftop serving commons/ stage (2007).257,191Clear Lake IntermediateBuilding-wide exhaust fan replacement164,807Clear Lake IntermediateReplace grease trap109,306Clear Lake IntermediateInstall insulated dog house over domestic water12,860Clear Lake IntermediateMDF-Rm 116A64,298Clear Lake IntermediateIDF6 - (new wing)64,298Clear Lake IntermediateIDF5-Rm 127 (Band Area)64,298Clear Lake IntermediateIDF5-Rm 127 (Band Area)64,298Clear Lake IntermediateIDF5-Rm 127 (Band Area)64,298Clear Lake IntermediateIDF5-Rm 127 (Band Area)64,298<	Clear Lake Intermediate	Replace existing modified bitumen roof.	4.791.472
Clear Lake IntermediateRegrade swells located behind school between staff parking lot and the school.12,860Clear Lake IntermediateRegrade grass areas around tennis courts to ensure positive drainage to storm sewer system.77,157Clear Lake IntermediateReplace fan coil unit serving rooms 119/ 12128,934Clear Lake IntermediateReplace fan coil unit serving custodial office28,934Clear Lake IntermediateReplace DX split system serving band hall addition (2007, 15 year average life cycle)192,893Clear Lake IntermediateReplace DX rooftop serving original band hall (2007).192,893Clear Lake IntermediateReplace DX rooftop serving admin (2007).192,893Clear Lake IntermediateReplace dual duct boxes serving original classroom area353,638Clear Lake IntermediateReplace (2) DX rooftop serving commons/ stage (2007).257,191Clear Lake IntermediateBuilding-wide exhaust fan replacement164,807Clear Lake IntermediateReplace grease trap109,306Clear Lake IntermediateInstall insulated dog house over domestic water backflow preventer.12,860Clear Lake IntermediateMDF-Rm 116A64,298Clear Lake IntermediateIDF6 - (new wing)64,298Clear Lake IntermediateIDF3-Rm 127 (Band Area)64,298Clear Lake IntermediateIDF3-Rm 124A64,298Clear		•	
Clear Lake Intermediate parking lot and the school. Clear Lake Intermediate Regrade grass areas around tennis courts to ensure positive drainage to storm sewer system. Clear Lake Intermediate Replace fan coil unit serving rooms 119/ 121 28,934 Clear Lake Intermediate Replace fan coil unit serving custodial office 28,934 Clear Lake Intermediate Replace DX split system serving band hall addition (2007, 15 year average life cycle) Clear Lake Intermediate Replace DX rooftop serving original band hall (2007). 192,893 Clear Lake Intermediate Replace DX rooftop serving admin (2007). 192,893 Clear Lake Intermediate Replace dual duct boxes serving original classroom area 353,638 Clear Lake Intermediate Replace (2) DX rooftop serving commons/ stage (2007). 257,191 Clear Lake Intermediate Building-wide exhaust fan replacement 164,807 Clear Lake Intermediate Replace grease trap 109,306 Clear Lake Intermediate Replace grease trap 109,306 Clear Lake Intermediate MDF-Rm 116A 64,298 Clear Lake Intermediate IDF6 - (new wing) 64,298 Clear Lake Intermediate IDF5 - Rm 127 (Band Area) 64,298 Clear Lake Intermediate IDF4 - (new wing) 64,298 Clear Lake Intermediate IDF3-Rm 127 (Band Area) 64,298 Clear Lake Intermediate IDF3-Rm 127 (Band Area) 64,298 Clear Lake Intermediate IDF3-Rm 127 (Band Area) 64,298 Clear Lake Intermediate IDF3-Rm 118 64,298 Clear Lake Intermediate IDF3-Rm 16 Ft. Office Workroom 64,298		•	
Clear Lake Intermediate Replace fan coil unit serving rooms 119/ 121 28,934 Clear Lake Intermediate Replace fan coil unit serving custodial office 28,934 Clear Lake Intermediate Replace DX split system serving band hall addition (2007, 15 year average life cycle) Clear Lake Intermediate Replace DX rooftop serving original band hall (2007). 192,893 Clear Lake Intermediate Replace DX rooftop serving admin (2007). 192,893 Clear Lake Intermediate Replace DX rooftop serving original classroom area 353,638 Clear Lake Intermediate Replace (2) DX rooftop serving commons/ stage (2007). 257,191 Clear Lake Intermediate Replace (2) DX rooftop serving commons/ stage (2007). 257,191 Clear Lake Intermediate Replace grease trap 109,306 Clear Lake Intermediate Replace grease trap 109,306 Clear Lake Intermediate MDF-Rm 116A 64,298 Clear Lake Intermediate IDF6 - (new wing) 64,298 Clear Lake Intermediate IDF5-Rm 127 (Band Area) 64,298 Clear Lake Intermediate IDF3-Rm224A 64,298 Clear Lake Intermediate IDF3-Rm 118 Clear Lake Intermediate IDF2-Rm 118 Clear Lake Intermediate IDF2-Rm 118 Clear Lake Intermediate IDF1-Rm 16 Ft. Office Workroom 64,298	Clear Lake Intermediate	_	12,860
Clear Lake Intermediate Replace DX rooftop serving original band hall (2007). 192,893 Clear Lake Intermediate Replace DX rooftop serving original band hall (2007). 192,893 Clear Lake Intermediate Replace DX rooftop serving original band hall (2007). 192,893 Clear Lake Intermediate Replace DX rooftop serving original classroom area 353,638 Clear Lake Intermediate Replace QDX rooftop serving original classroom area 353,638 Clear Lake Intermediate Replace (2) DX rooftop serving commons/ stage (2007). 257,191 Clear Lake Intermediate Replace (2) DX rooftop serving commons/ stage (2007). 257,191 Clear Lake Intermediate Building-wide exhaust fan replacement 164,807 Clear Lake Intermediate Replace grease trap 109,306 Clear Lake Intermediate Building-wide over domestic water backflow preventer. 12,860 Clear Lake Intermediate MDF-Rm 116A 64,298 Clear Lake Intermediate IDF6 - (new wing) 64,298 Clear Lake Intermediate IDF4 - (new wing) 64,298	Class Lake Internaciate	Regrade grass areas around tennis courts to ensure	77 157
Clear Lake IntermediateReplace fan coil unit serving custodial office28,934Clear Lake IntermediateReplace DX split system serving band hall addition (2007, 15 year average life cycle)192,893Clear Lake IntermediateReplace DX rooftop serving original band hall (2007).192,893Clear Lake IntermediateReplace DX rooftop serving admin (2007).192,893Clear Lake IntermediateReplace dual duct boxes serving original classroom area353,638Clear Lake IntermediateReplace (2) DX rooftop serving commons/ stage (2007).257,191Clear Lake IntermediateBuilding-wide exhaust fan replacement164,807Clear Lake IntermediateReplace grease trap109,306Clear Lake IntermediateInstall insulated dog house over domestic water backflow preventer.12,860Clear Lake IntermediateMDF-Rm 116A64,298Clear Lake IntermediateIDF6 - (new wing)64,298Clear Lake IntermediateIDF5-Rm 127 (Band Area)64,298Clear Lake IntermediateIDF4 - (new wing)64,298Clear Lake IntermediateIDF3-Rm224A64,298Clear Lake IntermediateIDF3-Rm224A64,298Clear Lake IntermediateIDF3-Rm 11864,298Clear Lake IntermediateIDF1-Rm 16 Ft. Office Workroom64,298	Clear Lake Intermediate	positive drainage to storm sewer system.	//,15/
Clear Lake Intermediate Replace DX split system serving band hall addition (2007, 15 year average life cycle) Clear Lake Intermediate Replace DX rooftop serving original band hall (2007). 192,893 Clear Lake Intermediate Replace DX rooftop serving admin (2007). 192,893 Clear Lake Intermediate Replace dual duct boxes serving original classroom area 353,638 Clear Lake Intermediate Replace (2) DX rooftop serving commons/ stage (2007). 257,191 Clear Lake Intermediate Building-wide exhaust fan replacement 164,807 Clear Lake Intermediate Replace grease trap 109,306 Clear Lake Intermediate Install insulated dog house over domestic water backflow preventer. Clear Lake Intermediate MDF-Rm 116A 64,298 Clear Lake Intermediate IDF6 - (new wing) Clear Lake Intermediate IDF5-Rm 127 (Band Area) Clear Lake Intermediate IDF4 - (new wing) Clear Lake Intermediate IDF3-Rm224A 64,298 Clear Lake Intermediate IDF3-Rm224A 64,298 Clear Lake Intermediate IDF2-Rm 118 64,298 Clear Lake Intermediate IDF1-Rm 16 Ft. Office Workroom 64,298	Clear Lake Intermediate	Replace fan coil unit serving rooms 119/ 121	28,934
Clear Lake Intermediate Replace DX rooftop serving original band hall (2007). 192,893 Clear Lake Intermediate Replace DX rooftop serving admin (2007). 192,893 Clear Lake Intermediate Replace DX rooftop serving admin (2007). 192,893 Clear Lake Intermediate Replace dual duct boxes serving original classroom area 353,638 Clear Lake Intermediate Replace (2) DX rooftop serving commons/ stage (2007). 257,191 Clear Lake Intermediate Building-wide exhaust fan replacement 164,807 Clear Lake Intermediate Replace grease trap 109,306 Clear Lake Intermediate Install insulated dog house over domestic water backflow preventer. Clear Lake Intermediate MDF-Rm 116A 64,298 Clear Lake Intermediate IDF6 - (new wing) Clear Lake Intermediate IDF5-Rm 127 (Band Area) Clear Lake Intermediate IDF4 - (new wing) Clear Lake Intermediate IDF3-Rm224A 64,298 Clear Lake Intermediate IDF2-Rm 118 64,298 Clear Lake Intermediate IDF1-Rm 16 Ft. Office Workroom 64,298	Clear Lake Intermediate	Replace fan coil unit serving custodial office	28,934
Clear Lake Intermediate Replace DX rooftop serving original band hall (2007). 192,893 Clear Lake Intermediate Replace DX rooftop serving admin (2007). 192,893 Clear Lake Intermediate Replace dual duct boxes serving original classroom area 353,638 Clear Lake Intermediate Replace (2) DX rooftop serving commons/ stage (2007). 257,191 Clear Lake Intermediate Building-wide exhaust fan replacement 164,807 Clear Lake Intermediate Replace grease trap 109,306 Clear Lake Intermediate Replace grease trap 109,306 Clear Lake Intermediate MDF-Rm 116A 64,298 Clear Lake Intermediate IDF6 - (new wing) 64,298 Clear Lake Intermediate IDF5-Rm 127 (Band Area) 64,298 Clear Lake Intermediate IDF4 - (new wing) 64,298 Clear Lake Intermediate IDF3-Rm224A 64,298 Clear Lake Intermediate IDF3-Rm224A 64,298 Clear Lake Intermediate IDF2-Rm 118 64,298 Clear Lake Intermediate IDF1-Rm 16 Ft. Office Workroom 64,298	Clear Lake Intermediate	Replace DX split system serving band hall addition	102 002
Clear Lake Intermediate Replace DX rooftop serving admin (2007). 192,893 Clear Lake Intermediate Replace dual duct boxes serving original classroom area 353,638 Clear Lake Intermediate Replace (2) DX rooftop serving commons/ stage (2007). 257,191 Clear Lake Intermediate Building-wide exhaust fan replacement 164,807 Clear Lake Intermediate Replace grease trap 109,306 Clear Lake Intermediate Install insulated dog house over domestic water backflow preventer. 12,860 Clear Lake Intermediate MDF-Rm 116A 64,298 Clear Lake Intermediate IDF6 - (new wing) 64,298 Clear Lake Intermediate IDF5-Rm 127 (Band Area) 64,298 Clear Lake Intermediate IDF4 - (new wing) 64,298 Clear Lake Intermediate IDF3-Rm224A 64,298 Clear Lake Intermediate IDF2-Rm 118 64,298 Clear Lake Intermediate IDF2-Rm 118 64,298 Clear Lake Intermediate IDF1-Rm 16 Ft. Office Workroom 64,298	Clear Lake Intermediate	(2007, 15 year average life cycle)	192,893
Clear Lake Intermediate Replace DX rooftop serving admin (2007). 192,893 Clear Lake Intermediate Replace dual duct boxes serving original classroom area 353,638 Clear Lake Intermediate Replace (2) DX rooftop serving commons/ stage (2007). 257,191 Clear Lake Intermediate Building-wide exhaust fan replacement 164,807 Clear Lake Intermediate Replace grease trap 109,306 Clear Lake Intermediate Install insulated dog house over domestic water backflow preventer. 12,860 Clear Lake Intermediate MDF-Rm 116A 64,298 Clear Lake Intermediate IDF6 - (new wing) 64,298 Clear Lake Intermediate IDF5-Rm 127 (Band Area) 64,298 Clear Lake Intermediate IDF4 - (new wing) 64,298 Clear Lake Intermediate IDF3-Rm224A 64,298 Clear Lake Intermediate IDF2-Rm 118 Clear Lake Intermediate IDF2-Rm 118 Clear Lake Intermediate IDF1-Rm 16 Ft. Office Workroom 64,298	Clear Lake Intermediate	Replace DX roofton serving original hand hall (2007)	102 803
Clear Lake Intermediate Replace (2) DX rooftop serving commons/ stage (2007). 257,191 Clear Lake Intermediate Building-wide exhaust fan replacement 164,807 Clear Lake Intermediate Replace grease trap 109,306 Clear Lake Intermediate Install insulated dog house over domestic water backflow preventer. 12,860 Clear Lake Intermediate MDF-Rm 116A 64,298 Clear Lake Intermediate IDF6 - (new wing) 64,298 Clear Lake Intermediate IDF5-Rm 127 (Band Area) 64,298 Clear Lake Intermediate IDF3-Rm224A 64,298 Clear Lake Intermediate IDF3-Rm224A 64,298 Clear Lake Intermediate IDF3-Rm 118 64,298 Clear Lake Intermediate IDF1-Rm 16 Ft. Office Workroom 64,298			
Clear Lake Intermediate Replace (2) DX rooftop serving commons/ stage (2007). 257,191 Clear Lake Intermediate Building-wide exhaust fan replacement 164,807 Clear Lake Intermediate Replace grease trap 109,306 Clear Lake Intermediate Install insulated dog house over domestic water backflow preventer. Clear Lake Intermediate MDF-Rm 116A 64,298 Clear Lake Intermediate IDF6 - (new wing) 64,298 Clear Lake Intermediate IDF5-Rm 127 (Band Area) 64,298 Clear Lake Intermediate IDF4 - (new wing) 64,298 Clear Lake Intermediate IDF3-Rm224A 64,298 Clear Lake Intermediate IDF3-Rm224A 64,298 Clear Lake Intermediate IDF3-Rm 118 64,298 Clear Lake Intermediate IDF1-Rm 16 Ft. Office Workroom 64,298	Clear Lake Intermediate	Replace DX Tooltop Serving autilii (2007).	192,093
Clear Lake IntermediateBuilding-wide exhaust fan replacement164,807Clear Lake IntermediateReplace grease trap109,306Clear Lake IntermediateInstall insulated dog house over domestic water backflow preventer.12,860Clear Lake IntermediateMDF-Rm 116A64,298Clear Lake IntermediateIDF6 - (new wing)64,298Clear Lake IntermediateIDF5-Rm 127 (Band Area)64,298Clear Lake IntermediateIDF4 - (new wing)64,298Clear Lake IntermediateIDF3-Rm224A64,298Clear Lake IntermediateIDF2-Rm 11864,298Clear Lake IntermediateIDF1-Rm 16 Ft. Office Workroom64,298	Clear Lake Intermediate	Replace dual duct boxes serving original classroom area	353,638
Clear Lake IntermediateReplace grease trap109,306Clear Lake IntermediateInstall insulated dog house over domestic water backflow preventer.12,860Clear Lake IntermediateMDF-Rm 116A64,298Clear Lake IntermediateIDF6 - (new wing)64,298Clear Lake IntermediateIDF5-Rm 127 (Band Area)64,298Clear Lake IntermediateIDF4 - (new wing)64,298Clear Lake IntermediateIDF3-Rm224A64,298Clear Lake IntermediateIDF2-Rm 11864,298Clear Lake IntermediateIDF1-Rm 16 Ft. Office Workroom64,298	Clear Lake Intermediate	Replace (2) DX rooftop serving commons/ stage (2007).	257,191
Clear Lake IntermediateReplace grease trap109,306Clear Lake IntermediateInstall insulated dog house over domestic water backflow preventer.12,860Clear Lake IntermediateMDF-Rm 116A64,298Clear Lake IntermediateIDF6 - (new wing)64,298Clear Lake IntermediateIDF5-Rm 127 (Band Area)64,298Clear Lake IntermediateIDF4 - (new wing)64,298Clear Lake IntermediateIDF3-Rm224A64,298Clear Lake IntermediateIDF2-Rm 11864,298Clear Lake IntermediateIDF1-Rm 16 Ft. Office Workroom64,298	Clear Lake Intermediate	Building-wide exhaust fan replacement	164,807
Clear Lake IntermediateInstall insulated dog house over domestic water backflow preventer.12,860Clear Lake IntermediateMDF-Rm 116A64,298Clear Lake IntermediateIDF6 - (new wing)64,298Clear Lake IntermediateIDF5-Rm 127 (Band Area)64,298Clear Lake IntermediateIDF4 - (new wing)64,298Clear Lake IntermediateIDF3-Rm224A64,298Clear Lake IntermediateIDF2-Rm 11864,298Clear Lake IntermediateIDF1-Rm 16 Ft. Office Workroom64,298		·	•
Clear Lake IntermediateMDF-Rm 116A64,298Clear Lake IntermediateIDF6 - (new wing)64,298Clear Lake IntermediateIDF5-Rm 127 (Band Area)64,298Clear Lake IntermediateIDF4 - (new wing)64,298Clear Lake IntermediateIDF3-Rm224A64,298Clear Lake IntermediateIDF2-Rm 11864,298Clear Lake IntermediateIDF1-Rm 16 Ft. Office Workroom64,298	Clear Lake Intermediate	Install insulated dog house over domestic water	
Clear Lake IntermediateIDF6 - (new wing)64,298Clear Lake IntermediateIDF5-Rm 127 (Band Area)64,298Clear Lake IntermediateIDF4 - (new wing)64,298Clear Lake IntermediateIDF3-Rm224A64,298Clear Lake IntermediateIDF2-Rm 11864,298Clear Lake IntermediateIDF1-Rm 16 Ft. Office Workroom64,298	Classialis Internacións	·	64 200
Clear Lake IntermediateIDF5-Rm 127 (Band Area)64,298Clear Lake IntermediateIDF4 - (new wing)64,298Clear Lake IntermediateIDF3-Rm224A64,298Clear Lake IntermediateIDF2-Rm 11864,298Clear Lake IntermediateIDF1-Rm 16 Ft. Office Workroom64,298			
Clear Lake IntermediateIDF4 - (new wing)64,298Clear Lake IntermediateIDF3-Rm224A64,298Clear Lake IntermediateIDF2-Rm 11864,298Clear Lake IntermediateIDF1-Rm 16 Ft. Office Workroom64,298			
Clear Lake IntermediateIDF3-Rm224A64,298Clear Lake IntermediateIDF2-Rm 11864,298Clear Lake IntermediateIDF1-Rm 16 Ft. Office Workroom64,298			
Clear Lake IntermediateIDF2-Rm 11864,298Clear Lake IntermediateIDF1-Rm 16 Ft. Office Workroom64,298			
Clear Lake Intermediate IDF1-Rm 16 Ft. Office Workroom 64,298			
			•
LICAL LONG III CHINGLI III III III III III III III III III	Great Lake Intermediate	Clear Lake Intermediate Total	6,994,520

School Infrastructure		
Estimated Cost		
Facility Name	Item Description	(With Inflation)
	<u> </u>	
Creekside Intermediate	Lighting levels in kitchen has been flagged by inspector.	128,596
Creekside Intermediate	Replace walk-in cooler/freezer.	36,742
Creekside Intermediate	Kitchen hood exhaust fans	73,483
Creekside Intermediate	Supply and exhaust fans are at end of life expectancy (original to building).	400,101
Creekside Intermediate	IDF does not have dedicated air.	42,865
Creekside Intermediate	Commons area DX split systems need to be replaced. HP-62 is Carrier model 40RUAA. HP-61 is Carrier model 40RUAA.	85,730
Creekside Intermediate	MDF Rm 200A	61,236
Creekside Intermediate	IDF3 Rm161A	61,236
Creekside Intermediate	IDF2 Rm 417A Closet inside room.	61,236
	Creekside Intermediate Total	951,225
League City Intermediate	Regrade swale to ensure positive drainage.	13,245
League City Intermediate	Install area drains, regrade area, and connect to	33,113
	nearest existing storm sewer system.	
League City Intermediate	Replace parking and wallpack fixtures with LED.	331,134
League City Intermediate	Replace main circuit breaker in main switchboard.	125,831
League City Intermediate	Replace fluorescent lighting in the kitchen areas with LED.	33,113
League City Intermediate	Replace Rite heating boiler (1998).	298,020
League City Intermediate	Building-wide exhaust fan replacement.	165,767
League City Intermediate	Building-wide air handler replacement, except outdoor air handlers.	2,762,781
League City Intermediate	Replace Rheem-Ruud domestic water heater serving classroom wing.	44,703
League City Intermediate	Replace domestic water mixing valves in boiler room.	24,504
League City Intermediate	Replace domestic boiler serving kitchen.	6,623
League City Intermediate	Replace all drinking fountains building/campus-wide.	205,303
League City Intermediate	Install insulated dog house over domestic water backflow preventer	13,245
League City Intermediate	MDFA Rm 221	66,227
League City Intermediate	IDF2-OFFICE AREA Rm 420	66,227
League City Intermediate	IDF1-CLASSRMS END OF BLDG Rm 250A	66,227
	League City Intermediate Total	4,256,063

	Calcard La Carada and La Carad	
School Infrastructure		
Facility Name	Item Description	Estimated Cost (With Inflation)
Seabrook Intermediate	Replace thru-wall flashing at masonry walls.	78,382
Seabrook Intermediate	Replace existing modified roof at gym.	230,714
Seabrook Intermediate	Replace all gutters.	71,850
Seabrook Intermediate	Replace Siemens 2500A outdoor switchboard section at east plant	379,080
Seabrook Intermediate	Replace disconnect at Carrier chiller at east plant	8,748
Seabrook Intermediate	Replace DX portion of Band Hall AC System. Installed in 2004, it uses R22 refrigerant which is now obsolete.	174,960
Seabrook Intermediate	Remove motor starter panel in Mechanical rooms feeding air handlers and pump motor VFDs	5,832
Seabrook Intermediate	East Plant - Replace Sellers heating boilers (2002)	174,960
Seabrook Intermediate	East Plant - Carrier air-cooled chiller (1996)	349,920
Seabrook Intermediate	Building-wide ductwork replacement (approximately 70% of campus)	2,004,604
Seabrook Intermediate	Building-wide air handling equipment replacement, except 2015 addition/ renovation	3,388,649
Seabrook Intermediate	Replace Rheem-Ruud domestic water heater in science wing (2002)	39,366
Seabrook Intermediate	Replace domestic boiler in mezzanine above girl's locker room and remove storage tanks.	145,800
Seabrook Intermediate	Replace AO Smith domestic water boiler system/ storage tanks at east plant (1989)	145,800
Seabrook Intermediate	Replace all drinking fountains building/campus-wide.	157,464
Seabrook Intermediate Seabrook Intermediate	MDF Old Rest Room (by back of school) IDF2 Custodian area	58,320 58,320
	Seabrook Intermediate Total	7,472,769
Space Center Intermediate	Remove, regrade, and replace sections of concrete pavement that have sunk and hold water.	34,992
Space Center Intermediate	Remove and replace sections of cracked concrete sidewalk.	13,997
Space Center Intermediate	Remove and replace cracked concrete curb.	583
Space Center Intermediate	Replace HID parking lot fixtures, wall pack fixtures and canopy fixtures with LED fixtures.	291,600

School Infrastructure		
Facility Name	Item Description	Estimated Cost (With Inflation)
Space Center Intermediate	Replace 3000A main circuit breaker	110,808
•	Replace Rite hydronic heating boiler and associated	•
Space Center Intermediate	pumps/valves (1998).	437,400
Space Center Intermediate	Building-wide exhaust fan replacement	145,955
Space Center Intermediate	Building-wide air handler replacement, except outdoor air handlers	3,502,923
Space Center Intermediate	Replace Raypak domestic water boiler and storage tank (1998)	145,800
Space Center Intermediate	Replace domestic water mixing valves in boiler room	21,578
Space Center Intermediate	Replace all drinking fountains building/campus-wide.	180,792
Space Center Intermediate	Remove water softener	4,666
Space Center Intermediate	Install insulated dog house over domestic water backflow preventer.	11,664
Space Center Intermediate	Add trap primers to floor drains in commons mezzanine and main mechanical room	46,656
Space Center Intermediate	MDF A-Rm 221-Servers	58,320
Space Center Intermediate	IDF4-Portable	87,480
Space Center Intermediate	IDF2 - Rm 420 Ft office	58,320
	Space Center Intermediate Total	5,153,534
Victory Lakes Intermediate	Replace existing EPMD roof with modified bitumen roof.	4,974,765
Victory Lakes Intermediate	Remove, regrade, and replace a section of concrete pavement that hold water.	55,112
Victory Lakes Intermediate	Remove and replace cracked concrete pavement and drive in front of school.	7,348
Victory Lakes Intermediate	Replace all supply and exhaust fans building wide and add EMS start stop control.	162,221
Victory Lakes Intermediate	Replace air handling units throughout	4,325,883
Victory Lakes Intermediate	Replace (2) BAC cooling towers (2002).	459,270
Victory Lakes Intermediate	(1) Sellers heating water boiler (2002).	275,562
Victory Lakes Intermediate	Replace domestic water mixing valves in coach's office	22,657
Victory Lakes Intermediate	Replace all drinking fountains building/campus-wide.	183,708
Victory Lakes Intermediate	Install insulated dog house over domestic water backflow preventer.	12,247
	Victory Lakes Intermediate Total	10,478,773

Proposed Bonds 2023 Recap

School Infractructure		
School Infrastructure		
Facility Name	Item Description	Estimated Cost (With Inflation)
	<u> </u>	
Westbrook Intermediate	Remove and replace cracked concrete sidewalk.	13,245
Westbrook Intermediate	Replace VFDs at air handlers.	231,794
Westbrook Intermediate	Replace roof mounted exhaust fans.	174,873
Westbrook Intermediate	Replace (3) Trane water-cooled chillers (2004).	1,258,308
Westbrook Intermediate	Replace (3) primary chilled water pumps.	198,680
Westbrook Intermediate	Replace (3) condenser water pumps.	198,680
Westbrook Intermediate	Replace (2) secondary chilled water pumps.	132,453
Westbrook Intermediate	Replace (2) Marley cooling towers (2004).	496,701
Westbrook Intermediate	Provide VFD for primary heating water pump and replace VFD for secondary heating water pump.	72,849
Westbrook Intermediate	Add bypass on chilled water loop with motorized valve,	49,670
Westbrook Intermediate	remove existing bypass. (1) Sellers heating water boiler (2004).	298,020
Westbrook Intermediate	Install insulated dog house over domestic water	13,245
Westbrook Intermediate	backflow preventer. (1) Sellers domestic water boiler (2004) serving athletics area	165,567
Westbrook Intermediate	MDF1-A-RM196 office	66,227
Westbrook Intermediate	IDF3-A Portable (P501)	99,340
Westbrook Intermediate	IDF2-RM160 (main hallway)	66,227
Westbrook Intermediate	IDF1-RM236	66,227
	Westbrook Intermediate Total	3,602,106
Armand Bayou Elementary	Reseal all windows, expansion joints and control joints.	90,017
Armand Bayou Elementary	Replace existing skylights.	171,032
Armand Bayou Elementary	Replace existing EPDM roof at high gym and connecting hallway with modified bitumen roof.	264,714
Armand Bayou Elementary	Building - Seal exterior penetrations	6,430
Armand Bayou Elementary	Site - Replace walking track with 8 foot concrete walking track	154,315
Armand Bayou Elementary	Sidewalk	165,503
Armand Bayou Elementary	No ramp at playground includes concrete sidewalk	32,149
Armand Bayou Elementary	Exterior Lighting	22,906
Armand Bayou Elementary	Replace double convection oven.	32,149
Armand Bayou Elementary	Hydronic piping	189,162
Armand Bayou Elementary	Gym gas heaters	61,083

Prepared By:

Proposed Bonds 2023 Recap		
School Infrastructure		
Facility Name	Item Description	Estimated Cost (With Inflation)
Armand Bayou Elementary	Gym DX split systems	32,149
Armand Bayou Elementary	Chillers (1)	482,234
Armand Bayou Elementary	Chiller 2 - 2005 Model	321,489
Armand Bayou Elementary	Install insulated dog house over domestic water	12,860
Almand Bayou Elementary	backflow preventer	12,800
Armand Bayou Elementary	MDF (Back By The Labs)	64,298
Armand Bayou Elementary	IDF2 (Art Storage Room)	64,298
Armand Bayou Elementary	IDF1 (old principals office area)	64,298
	Armand Bayou Elementary Total	2,231,086
Bauerschlag Elementary	4'6" x 6' single pane aluminum - 32 front /16 Right side / 36 backside	77,883
Bauerschlag Elementary	Site - Improve grading at playground to reduce ponding and fill any existing holes.	119,208
Bauerschlag Elementary	Main Switchgear	66,227
Bauerschlag Elementary	Main Switchgear	66,227
Bauerschlag Elementary	Exterior lighting	93,960
Bauerschlag Elementary	Water Cooled Chillers (3)	1,490,102
Bauerschlag Elementary	Hydronic piping at plant	19,868
Bauerschlag Elementary	Hot water pumps	41,392
Bauerschlag Elementary	Exhaust Fans	79,472
Bauerschlag Elementary	Cooling Towers	264,907
Bauerschlag Elementary	Condenser Water pump	198,680
Bauerschlag Elementary	Chilled water pumps	173,845
Bauerschlag Elementary	Boiler	107,618
Bauerschlag Elementary	Dual Duct terminal units	317,888
Bauerschlag Elementary	Existing water heaters - 1 replaced recently, 2 original	7,947
Bauerschlag Elementary	Existing Kitchen Water heater	44,703
Bauerschlag Elementary	Kitchen hood	6,623
Bauerschlag Elementary	floor drains	49,670
Bauerschlag Elementary	MDF Rm. 153	66,227
Bauerschlag Elementary	IDF2 Rm. 265 (Café Storage)	66,227
Bauerschlag Elementary	IDF1 Rm. 201	66,227
	Bauerschlag Elementary Total	3,424,901
Bay Elementary	Reseal all windows and control joints.	61,236
Bay Elementary	Site - Provide sidewalks to playgrounds	64,298
Bay Elementary	Provide a 8 foot wide concrete walking track	146,966
Bay Elementary	Replace marquee with digital marquee.	91,854
Bay Elementary	Exterior lighting - Upgrade exterior lighting to LED	95,681

School Infrastructure		
Facility Name	Item Description	Estimated Cost (With Inflation)
Bay Elementary	Exterior Lighting - Replace HID wall pack fixtures and	21,815
	canopy fixtures with LED fixtures	
Bay Elementary	Electrical Panels	24,494
Bay Elementary	Replace reach-in cooler (single door).	39,803
Bay Elementary	Replace reach in warmer (single door).	22,045
Bay Elementary	Replace dishwasher.	48,569
Bay Elementary	Replace convection oven.	64,169
Bay Elementary	Cooling Towers	581,742
Bay Elementary	range hood	1,837
Bay Elementary	Kitchen hood	6,124
Bay Elementary	Install insulated dog house over domestic water	12,247
·	backflow preventer	
Bay Elementary	MDF Rm. 401 (Lib Office)	61,236
Bay Elementary	IDF1 Rm. 614	61,236
	Bay Elementary Total	1,405,352
Brookwood Elementary	Replace existing skylights.	38,579
Brookwood Elementary	Replace existing skylights. Replace existing metal roof.	1,711,968
Brookwood Elementary	Building - Replace gutters and downspouts	214,755
brookwood Elementary	building - Replace gutters and downspouts	214,733
Brookwood Elementary	Replace asphalt walking track to 8' wide concrete.	154,315
Proplywood Flomentary	Exterior Lighting - Replace HID wall pack fixtures and	22.006
Brookwood Elementary	canopy fixtures with LED fixtures	22,906
Brookwood Elementary	Exterior lighting	32,149
Brookwood Elementary	Replace walk-in cooler/freezer.	38,579
Brookwood Elementary	Replace reach-in cooler (single door).	41,794
Brookwood Elementary	Replace reach in warmer (single door).	23,147
Brookwood Elementary	Replace dishwasher.	50,997
Brookwood Elementary	Replace convection oven.	83,587
Brookwood Elementary	Exhaust Fans	119,594
Brookwood Elementary	Cooling Towers	305,415
Brookwood Elementary	Condenser Water pump	128,596
Brookwood Elementary	Kitchen hood	6,430
Drackwood Flomentary	Install insulated dog house over domestic water	12.960
Brookwood Elementary	backflow preventer	12,860
Brookwood Elementary	domestic water piping	19,289
Brookwood Elementary	MDF Rm. 225	64,298
Brookwood Elementary	IDF2 Rm. 125A (music storage)	64,298
Brookwood Elementary	Cabling	193,237
	Brookwood Elementary Total	3,326,793

School Infrastructure		
		Estimated Cost
Facility Name	Item Description	(With Inflation)
		(vvitii iiiiiatioii)
Clear Lake City Elementary	Reseal all windows and control joints.	90,017
Clear Lake City Elementary	Replace Modified Roof	2,481,332
· · · · · · · · · · · · · · · · · · ·	Boiler	
Clear Lake City Elementary		104,484
Clear Lake City Elementary	Air Cooled Chiller - Gym MDF	1,446,701
Clear Lake City Elementary Clear Lake City Elementary		64,298
Clear Lake City Elementary	IDF1(Front office) Clear Lake City Elementary Total	64,298 4,251,130
	Clear Lake City Liementary Total	4,231,130
Falcon Pass Elementary	Reseal all windows and control joints.	81,648
Falcon Pass Elementary	Window Wet Glazing	68,584
Falcon Pass Elementary	Site - Correct drainage issue at playground	34,992
Falcon Pass Elementary	Exterior lighting	83,835
Falcon Pass Elementary	Water Cooled Chillers	1,530,900
Falcon Pass Elementary	Replace domestic boiler serving kitchen.	94,770
Falcon Pass Elementary	Hot water pumps	36,450
Falcon Pass Elementary	Exhaust Fans	69,984
Falcon Pass Elementary	Dual Duct terminal units	279,936
Falcon Pass Elementary	Cooling Towers	233,280
Falcon Pass Elementary	Condenser Water pump	174,960
Falcon Pass Elementary	Chilled water pumps	153,090
Falcon Pass Elementary	AHUs	326,592
Falcon Pass Elementary	water heaters	27,994
Falcon Pass Elementary	Lift Station	34,992
Falcon Pass Elementary	Kitchen Water heater	39,366
Falcon Pass Elementary	Kitchen hood	5,832
Falcon Pass Elementary	MDF Rm. 153	58,320
Falcon Pass Elementary	IDF2 (Café Storage)	58,320
Falcon Pass Elementary	IDF1 Rm. 201	58,320
	Falcon Pass Elementary Total	3,452,165
Ferguson Elementary	Replace existing modified bitumen roof.	974,562
Ferguson Elementary	Exterior lighting	28,130
Ferguson Elementary	Variable Frequency Drives	6,430
Ferguson Elementary	Exhaust Fans	119,594
Ferguson Elementary	Cooling Towers	305,415
Ferguson Elementary	Condenser Water pump	257,191
Ferguson Elementary	waste vent piping	96,618
Ferguson Elementary	Kitchen hood	6,430
Ferguson Elementary	domestic water piping	257,649
Ferguson Elementary	Domestic water	19,289
Ferguson Elementary	Domestic Water	12,860

School Infrastructure		
		Estimated Cost
Facility Name	Item Description	(With Inflation)
Ferguson Elementary	MDF Rm. 224	64,298
Ferguson Elementary	IDF2 Rm. 404	64,298
	Ferguson Elementary Total	2,212,764
Cilmara Flamentary	Exterior lighting	111 750
Gilmore Elementary	Exterior lighting	111,758
Gilmore Elementary	Water Cooled Chillers (3)	1,490,102
Gilmore Elementary	Variable Frequency Drives	39,736
Gilmore Elementary	Hydronic piping at plant	19,868
Gilmore Elementary	Hot water pumps	41,392
Gilmore Elementary	Exhaust Fans	79,472
Gilmore Elementary	Condenser Water pump	198,680
Gilmore Elementary	Chilled water pumps	173,845
Gilmore Elementary	Boiler	107,618
Gilmore Elementary	Dual Duct terminal units	317,888
Gilmore Elementary	Cooling unit in main electrical room	29,802
Gilmore Elementary	Replace water heater.	23,842
Gilmore Elementary	Replace kitchen water heater.	44,703
Gilmore Elementary	MDF Rm.201	66,227
Gilmore Elementary	IDF3 (portable)	99,340
Gilmore Elementary	IDF2 Rm. 284 A/B (room inside another room)	66,227
Gilmore Elementary	IDF1 Rm. 111	66,227
·	Gilmore Elementary Total	2,976,727
Goforth Elementary	Regrade site	119,208
Goforth Elementary	Site - Provide accessible route to playground	13,245
Goforth Elementary	Drainage	4,967
Goforth Elementary	Main Switchgear	66,227
Goforth Elementary	Exterior lighting	62,088
Goforth Elementary	Hydronic piping at plant	19,868
Goforth Elementary	Water Cooled Chillers (3)	1,490,102
Goforth Elementary	Hot water pumps	41,392
Goforth Elementary	Exhaust Fans	79,472
Goforth Elementary	Cooling Towers	264,907
Goforth Elementary	Condenser Water pump	198,680
Goforth Elementary	Chilled water pumps	115,897
Goforth Elementary	Boiler	107,618
Goforth Elementary	Dual Duct terminal units	317,888
Goforth Elementary	Kitchen hood	6,623
Goforth Elementary	Domestic Water	13,245
Goforth Elementary	MDF Rm. 153	66,227
Colorul Lielliellal y	INIDI IVIII. 193	00,227

School Infrastructure		
Facility Name		Estimated Cost
Facility Name	Item Description	(With Inflation)
Goforth Elementary	IDF2 (Café)	66,227
Goforth Elementary	IDF1 Rm. 201	66,227
	Goforth Elementary Total	3,120,108
Greene Elementary	Building - Replace electrical outlets	13,997
Greene Elementary	Replace walk-in cooler/freezer.	34,992
Greene Elementary	Replace milk cooler.	8,165
Greene Elementary	Replace convection ovens.	58,320
Greene Elementary	All preparation sinks and 3-compartment sink drain improperly.	122,472
Greene Elementary	Replace DX Units (1996) - Old Gym / Storage	51,030
Greene Elementary	Hydronic piping	6,998
Greene Elementary	Gym Chiller & pump	510,300
Greene Elementary	Sanitary	29,160
Greene Elementary	Domestic Water	11,664
Greene Elementary	MDF Rm. 505 (library)	58,320
Greene Elementary	IDF2 (portable T7)	58,320
Greene Elementary	IDF1 Rm. 112 (small walkway near café)	58,320
,	Greene Elementary Total	1,022,058
Hyde Elementary	Replace thru-wall flashing.	76,423
Hyde Elementary	Provide roof access ladders.	9,798
Hyde Elementary	Replace existing skylights.	279,236
Hyde Elementary	Replace existing EPDM roof with modified bitumen roof.	2,860,067
Hyde Elementary	Site - Provide 8 foot wide concrete walking track	146,966
Hyde Elementary	Exterior lighting	30,618
Hyde Elementary	Replace walk-in cooler/freezer.	36,742
Hyde Elementary	Replace reach-in cooler (single door).	39,803
Hyde Elementary	Replace reach in warmer (single door).	22,045
Hyde Elementary	Replace dishwasher.	48,569
Hyde Elementary	Replace convection oven.	63,685
Hyde Elementary	Milk box remodel	490
Hyde Elementary	Variable Frequency Drives	42,865
Hyde Elementary	Hot water pumps	38,273
Hyde Elementary	Exhaust Fans	102,876
Hyde Elementary	Condenser Water pump	122,472
Hyde Elementary	Chilled water pumps	107,163
Hyde Elementary	Existing water heaters - 1 replaced recently, 2 original	7,348

Proposed Bonds 2023 Recap

School Infrastructure		
		Estimated Cost
Facility Name	Item Description	(With Inflation)
Illuda Flamantam	Domostic Water	12 247
Hyde Elementary	Domestic Water	12,247
Hyde Elementary	MDF (library storage room) Hyde Elementary Total	61,236 4,108,922
	· · · · · · · · · · · · · · · · · · ·	· · ·
McWhirter Elementary	Replace existing EPDM roof at detached gym with modified bitumen roof.	156,758
McWhirter Elementary	Provide accessible ramp at back parking lot	3,858
McWhirter Elementary	faucets	123,452
McWhirter Elementary	Art and science Classroom Sinks	5,144
McWhirter Elementary	IDF4 (old gym)	96,447
	McWhirter Elementary Total	385,659
Mossman Elementary	Exterior lighting - Replace HID parking lot fixtures, wall pack fixtures and canopy fixtures with LED	60,279
Mossman Elementary	Variable Frequency Drives	51,438
Mossman Elementary	Domestic Water	12,860
Mossman Elementary	MDF Rm. 1022	64,298
Mossman Elementary	IDF4 (Portable)	96,447
Mossman Elementary	IDF3 Rm. 6011 (commons MDF)	64,298
Mossman Elementary	IDF2 Rm. 1429	64,298
Mossman Elementary	IDF1 Rm. 1042	64,298
	Mossman Elementary Total	478,216
North Pointe Elementary	Exterior lighting	26,791
North Pointe Elementary	Replace walk-in cooler/freezer.	36,742
North Pointe Elementary	Replace reach-in cooler (single door).	19,902
North Pointe Elementary	Replace reach-in cooler (single door pass through).	19,902
North Pointe Elementary	Replace reach in warmer (single door).	11,022
North Pointe Elementary	Replace reach in warmer (single door pass through).	14,084
North Pointe Elementary	Replace dishwasher.	48,569
North Pointe Elementary	Replace convection oven.	63,685
North Pointe Elementary	Milk box remodel	490
North Pointe Elementary	Hydronic piping at plant	18,371
North Pointe Elementary	Hot water pumps	76,545
North Pointe Elementary	Variable Frequency Drives	21,433
North Pointe Elementary	Condenser Water pump	183,708
North Pointe Elementary	Chilled water pumps	160,745
North Pointe Elementary	Fan Coil Units	7,348
North Pointe Elementary	Exhaust Fans	106,551

Prepared By:

	School Infrastructure	
Facility Name	Item Description	Estimated Cost (With Inflation)
North Pointe Elementary	Kitchen hood	6,124
North Pointe Elementary	Domestic Water - Install insulated dog house over domestic water backflow preventor	12,247
North Pointe Elementary	Domestic water - add Backflow preventor	12,247
North Pointe Elementary	Existing water heaters - 1 replaced recently, 2 original	7,348
North Pointe Elementary North Pointe Elementary	MDF (library) IDF1 (office)	61,236 61,236
North Fointe Elementary	North Pointe Elementary Total	976,326
Daw Flancists	Fatorica Unlation	
Parr Elementary Parr Elementary	Exterior Lighting Boilers	64,298 208,968
Parr Elementary	Water Heater	23,147
Parr Elementary	Kitchen Water heater	43,401
Parr Elementary	Domestic Water	12,860
Parr Elementary	MDF Rm. 426	64,298
Parr Elementary	IDF2 Rm. 119 C/E (upstairs through mezzanine)	64,298
Darr Clamanta:	IDE4 D 442	64.200
Parr Elementary	IDF1 Rm. 412	64,298
Pair Elementary	Parr Elementary Total	545,568
Robinson Elementary		
	Parr Elementary Total Site - Regrade/provide inlets for proper site drainage at	545,568
Robinson Elementary	Site - Regrade/provide inlets for proper site drainage at Southeast lawn.	545,568 158,944
Robinson Elementary Robinson Elementary	Site - Regrade/provide inlets for proper site drainage at Southeast lawn. Site - Provide 8 foot wide concrete walking track	158,944 158,944
Robinson Elementary Robinson Elementary Robinson Elementary	Site - Regrade/provide inlets for proper site drainage at Southeast lawn. Site - Provide 8 foot wide concrete walking track Surge Protector Devices	158,944 158,944 16,557
Robinson Elementary Robinson Elementary Robinson Elementary Robinson Elementary	Site - Regrade/provide inlets for proper site drainage at Southeast lawn. Site - Provide 8 foot wide concrete walking track Surge Protector Devices Exterior lighting	158,944 158,944 16,557 115,897
Robinson Elementary Robinson Elementary Robinson Elementary Robinson Elementary Robinson Elementary	Site - Regrade/provide inlets for proper site drainage at Southeast lawn. Site - Provide 8 foot wide concrete walking track Surge Protector Devices Exterior lighting Water Cooled Chillers (2)	158,944 158,944 158,944 16,557 115,897 1,152,694
Robinson Elementary Robinson Elementary Robinson Elementary Robinson Elementary Robinson Elementary Robinson Elementary	Site - Regrade/provide inlets for proper site drainage at Southeast lawn. Site - Provide 8 foot wide concrete walking track Surge Protector Devices Exterior lighting Water Cooled Chillers (2) Make up air units	158,944 158,944 16,557 115,897 1,152,694 317,888
Robinson Elementary	Site - Regrade/provide inlets for proper site drainage at Southeast lawn. Site - Provide 8 foot wide concrete walking track Surge Protector Devices Exterior lighting Water Cooled Chillers (2) Make up air units Hot water pumps	158,944 158,944 16,557 115,897 1,152,694 317,888 41,392
Robinson Elementary	Site - Regrade/provide inlets for proper site drainage at Southeast lawn. Site - Provide 8 foot wide concrete walking track Surge Protector Devices Exterior lighting Water Cooled Chillers (2) Make up air units Hot water pumps FCUs	158,944 158,944 16,557 115,897 1,152,694 317,888 41,392 33,113
Robinson Elementary	Site - Regrade/provide inlets for proper site drainage at Southeast lawn. Site - Provide 8 foot wide concrete walking track Surge Protector Devices Exterior lighting Water Cooled Chillers (2) Make up air units Hot water pumps FCUs Exhaust Fans	158,944 158,944 16,557 115,897 1,152,694 317,888 41,392 33,113 75,498
Robinson Elementary	Site - Regrade/provide inlets for proper site drainage at Southeast lawn. Site - Provide 8 foot wide concrete walking track Surge Protector Devices Exterior lighting Water Cooled Chillers (2) Make up air units Hot water pumps FCUs Exhaust Fans Dual Duct mixing boxes	158,944 158,944 158,944 16,557 115,897 1,152,694 317,888 41,392 33,113 75,498 317,888
Robinson Elementary	Site - Regrade/provide inlets for proper site drainage at Southeast lawn. Site - Provide 8 foot wide concrete walking track Surge Protector Devices Exterior lighting Water Cooled Chillers (2) Make up air units Hot water pumps FCUs Exhaust Fans Dual Duct mixing boxes Cooling Towers Condenser Water pumps Chilled water pumps	158,944 158,944 158,944 16,557 115,897 1,152,694 317,888 41,392 33,113 75,498 317,888 264,907 132,453 231,794
Robinson Elementary	Site - Regrade/provide inlets for proper site drainage at Southeast lawn. Site - Provide 8 foot wide concrete walking track Surge Protector Devices Exterior lighting Water Cooled Chillers (2) Make up air units Hot water pumps FCUs Exhaust Fans Dual Duct mixing boxes Cooling Towers Condenser Water pumps Boilers	158,944 158,944 16,557 115,897 1,152,694 317,888 41,392 33,113 75,498 317,888 264,907 132,453 231,794 107,618
Robinson Elementary	Site - Regrade/provide inlets for proper site drainage at Southeast lawn. Site - Provide 8 foot wide concrete walking track Surge Protector Devices Exterior lighting Water Cooled Chillers (2) Make up air units Hot water pumps FCUs Exhaust Fans Dual Duct mixing boxes Cooling Towers Condenser Water pumps Chilled water pumps Boilers Water Heater	158,944 158,944 158,944 16,557 115,897 1,152,694 317,888 41,392 33,113 75,498 317,888 264,907 132,453 231,794 107,618 23,842
Robinson Elementary	Site - Regrade/provide inlets for proper site drainage at Southeast lawn. Site - Provide 8 foot wide concrete walking track Surge Protector Devices Exterior lighting Water Cooled Chillers (2) Make up air units Hot water pumps FCUs Exhaust Fans Dual Duct mixing boxes Cooling Towers Condenser Water pumps Boilers	158,944 158,944 16,557 115,897 1,152,694 317,888 41,392 33,113 75,498 317,888 264,907 132,453 231,794 107,618

Proposed Bonds 2023 Recap

School Infrastructure		
Facility Name	Item Description	Estimated Cost (With Inflation)
Robinson Elementary	IDF2 Rm. 197 (café storage)	66,227
Robinson Elementary	IDF1 Rm. 157B	66,227
	Robinson Elementary Total	3,392,813
Stewart Elementary	Building Envelope - Repair brick	39,736
Stewart Elementary	Site concrete repair	39,736
Stewart Elementary	Milk Box	530
Stewart Elementary	Kitchen Water heater	44,703
Stewart Elementary	Kitchen hood	6,623
Stewart Elementary	Domestic Water	13,245
Stewart Elementary	MDF Rm. 235 (Library)	66,227
Stewart Elementary	IDF2 Rm. 319	66,227
Stewart Elementary	IDF1 Rm.214	66,227
	Stewart Elementary Total	343,254
Mand Flamanton	December 11 windows and control in into	75.000
Ward Elementary	Reseal all windows and control joints.	75,600
Ward Elementary	Replace existing EPDM	57,132
Ward Elementary	Site - Replace gravel dirt track with 8foot wide concrete walking track	129,600
Ward Elementary	Exterior lighting	23,625
Ward Elementary	Electrical panels	10,800
Ward Elementary	Replace walk-in cooler/freezer.	32,400
Ward Elementary	Replace reach-in cooler (single door).	35,100
Ward Elementary	Replace reach in warmer (single door).	19,440
Ward Elementary	Replace dishwasher.	42,830
Ward Elementary	Replace convection oven.	56,160
Ward Elementary	Cooling Towers	256,500
Ward Elementary	Condenser Water pump	162,000
Ward Elementary	Kitchen hood	5,400
Ward Elementary	Domestic water	16,200
Ward Elementary	Domestic Water	10,800
Ward Elementary	MDF Rm. 224	54,000
	Ward Elementary Total	987,587
Weber Elementary	Exterior lighting. Parking lot - Provide additional site lighting for parking area	76,545
Weber Elementary	Dual Duct terminal units	279,936
Weber Elementary	Water Cooled Chillers (3)	1,312,200
vveber Elementary	VFDs	1,312,200 291,600
Meher Flementary	V1.175	Z91,0U(
Weber Elementary		
Weber Elementary Weber Elementary Weber Elementary	Replace domestic boiler serving kitchen. Hot water pumps	94,770 36,450

Prepared By:

Proposed Bonds 2023 Recap

School Infrastructure		
Facility Name	Item Description	Estimated Cost (With Inflation)
Wahar Flamonton	Cooling Towers	FF4 040
Weber Elementary	Cooling Towers	554,040
Weber Elementary	Condenser Water piping	116,640
Weber Elementary	Chilled and condenser water pumps	102,060
Weber Elementary	Kitchen hood	5,832
Weber Elementary	Domestic Water	11,664
Weber Elementary	Existing water heaters - 2 replaced recently, 1 original (2002)	6,998
Weber Elementary	Existing Kitchen Water heater - 2002	39,366
Weber Elementary	MDF Rm. 147	58,320
Weber Elementary	IDF3 portable	87,480
Weber Elementary	IDF2 Rm. 252 (café storage)	58,320
Weber Elementary	IDF1 Rm. 194	58,320
	Weber Elementary Total	3,260,525
Wedgewood Elementary	Replace gutters at metal roof locations.	49,767
Wedgewood Elementary	Replace existing standing seam roof.	2,313,949
Wedgewood Elementary	Exterior lighting. Site - Replace site lighting with LED fixtures and new light poles	60,279
Wedgewood Elementary	Replace walk-in cooler/freezer.	38,579
Wedgewood Elementary	Replace reach-in cooler (single door).	41,794
Wedgewood Elementary	Replace reach in warmer (single door).	23,147
Wedgewood Elementary	Replace dishwasher.	50,997
Wedgewood Elementary	Replace convection oven.	66,870
Wedgewood Elementary	Cooling Towers	305,415
Wedgewood Elementary	Water heaters	7,716
Wedgewood Elementary	waste vent piping	64,412
Wedgewood Elementary	Kitchen hood	6,430
Wedgewood Elementary	Domestic water	19,289
Wedgewood Elementary	Domestic Water	12,860
Wedgewood Elementary	MDF Rm. 224	64,298
,	Wedgewood Elementary Total	3,125,802
Bay Professional Learning	Replace existing EPDM roof with modified bitumen	240.640
Center	roof at Bay Professional Learning Center	219,648
Bay Professional Learning	IDE2 (Pay DLC Pm. 102)	102 220
Center	IDF3 (Bay PLC Rm. 102)	102,320
	Bay Professional Learning Center Total	321,968
Control Comment Fig. 119	Located LED high have lighting to the observer.	E42.400
Central Support Facility	Install LED high bay lighting in the shop area.	513,409
Central Support Facility	Exterior Lighting - Replace HID wall pack fixtures and canopy fixtures with LED fixtures	24,301
	canopy fixtures with LED fixtures	

Prepared By:

Operations Finance Manager

	Proposed Bonds 2023 Recap	
	School Infrastructure	
Facility Name	Item Description	Estimated Cost (With Inflation)
Central Support Facility	VAV AHUs, RTUs	1,232,182
Central Support Facility	Return air path	154,029
Central Support Facility	Main Electrical cooling	30,696
Central Support Facility	DX FCUs	17,053
Central Support Facility	ACCUs	122,784
Central Support Facility	Kitchen hood	6,821
Central Support Facility	MDF CSF Upstairs	409,281
	Central Support Facility Total	2,510,556
	E to destribute a Positive IIIP will and City and all	
Education Support Center	Exterior Lighting - Replace HID wall pack fixtures and	24,301
Education Comment Conton	canopy fixtures with LED fixtures	47.740
Education Support Center	Upstairs IDF does not have dedicated AC.	47,749
Education Support Center	Teledyne Laars Gas Boiler (Heat Pump Boiler)	109,142
Education Support Center	Mechanical motors on starters.	225,105
Education Support Center	Emerson unit for MDF (131) is outdated.	47,749
Education Support Center	Baldor condenser water pumps	136,427
Education Support Center	MDF (ESC)	68,214
Education Support Center	IDF1 (ESC upstairs)	68,214
	Education Support Center Total	726,901
Learner Support Center	Repair plaster wall/soffit.	6,821
Learner Support Center	Remove, regrade, and replace sections of concrete	0,021
Learner Support Center	pavement that have sunk and hold water in bus drop	10,232
Learner Support Center	off.	10,232
	Remove and replace existing Parking lots and drives	
Learner Support Center	throughout site.	2,251,047
Learner Support Center	Remove and replace cracked concrete sidewalk.	68,214
Learner Support Center	New concrete drive at entrance of northwest parking	30,696
	lot.	
Loornor Cunnart Contor	Exterior lighting - Replace HID parking lot fixtures, wall	42.622
Learner Support Center	pack fixtures and canopy fixtures with LED	42,633
	Exterior Lighting - Parking Lot, Wallpacks, Canopy	
Learner Support Center	Fixutres	341,068
Learner Support Center	Replace dishwasher.	54,103
Learner Support Center	Kitchen hood	6,821
Learner Support Center	Domestic Water - Backflow Preventer	13,643
Learner Support Center	Domestic Water	13,643
Learner Support Center	MDF (Main HW across from Special Programs)	68,214

Proposed Bonds 2023 Recap

School Infrastructure		
Facility Name	Item Description	Estimated Cost (With Inflation)
Learner Support Center	IDF2 (Front area)	68,214
Learner Support Center	IDF1 - New IDF past gym	68,214
• •	Learner Support Center Total	3,043,563
Main Transportation Center	Sanitary piping repairs and addition	409,281
Main Transportation Center	Trans. MDF	68,214
Main Transportation Center	Trans. IDF3 (new office room area)	68,214
Wall Transportation center	Main Transportation Center Total	545,709
	•	•
Technology Learning Center	Replace Roof	870,321
Technology Learning Center	Power - Receptacles	5,832
Technology Learning Center	HVAC	29,160
Technology Learning Center	Fan Powered terminal units	118,973
Technology Learning Center	exhaust fans	17,496
Technology Learning Center	TESTLAB	58,320
Technology Learning Center	MDF	58,320
Technology Learning Center	IDF 1	58,320
	Technology Learning Center Total	1,216,742
Maintenance Equipment Replacement	Scrubbers, Sweepers & Extractors	1,040,623
Maintenance Equipment Replacement	Scrubbers, Sweepers & Extractors	28,641
	Maintenance Equipment Replacement Total	1,069,264

School Infrastructure Grand Total \$ 130,314,363