

Bay Professional Learning Center

Category	Item Description	Estimated Cost (With Inflation)
School Infrastructure	Replace existing EPDM roof with modified bitumen roof at Bay Professional Learning Center	219,648
School Infrastructure	IDF3 (Bay PLC Rm. 102)	102,320
School Infrastructure Total		321,968

Bay Professional Learning Center Grand Total **\$ 321,968**